

WAD 2302  
4(a)  
3/23/05

MEMO TO THE FILE  
RHONE POULENC FACILITY  
EPA ID: WAD 00928 2302

At approximately 7:45 a.m., March 23, 2005, I visited the above reference site to determine if repairs to the security fence had been completed. Upon entering the site I encountered Jose of RCI. I observed that the temporary fence which used to transect the site north to south had been removed. I observed that the gap in the fence along slip 6 has been repaired. Jose stated that they now lock the front gate to insure security. I was able to enter the building and observe the GW treatment system. It had been manually turned off. I observed that the sink hard-plumbed into the system contained about 1 inch of purge water. Jose stated that the system had been turned off because it had been running 24-7 and they wanted to bring the water level back up. Jose also stated that they had to replace a transducer last week. The transducer and another electronic piece of the control box had shorted out as a result of a power surge the previous week. I opened the control panel and did not see an autodailer. Jose further stated that the modem had shorted out and they were currently working on it. At approximately 8:15 I departed the site.



Shawn Blocker  
ARCU Enforcement Officer